

51-3-1

315
51. 51.4.2
ELI LILLYSITE-SPECIFIC HEALTH AND SAFETY PLAN FOR
RCRA FACILITY ASSESSMENTS (RFA'S)

VISUAL SITE INSPECTIONS

SITE: Eli Lilly Industries, Inc. (809) 834-7846

LOCATION: State Rd. No. 2, Km 146.7; Mayaguez Puerto Rico 00709

DATE PREPARED: 7/3/87

PREPARED BY: Donna Choker / Ebasco Services Inc
(NAME/COMPANY)

SCHEDULED SITE VISIT DATE: August 4, 1987

REVISION: 0

EBASCO SERVICES INCORPORATED, EBASCO SUBCONTRACTORS AND THE UNITED STATES ENVIRONMENTAL PROTECTION AGENCY DO NOT GUARANTEE THE HEALTH OR SAFETY OF ANY PERSON ENTERING THIS SITE. DUE TO THE HAZARDOUS NATURE OF THIS SITE AND THE ACTIVITY OCCURRING THEREON, IT IS NOT POSSIBLE TO DISCOVER, EVALUATE, AND PROVIDE PROTECTION FOR ALL POSSIBLE HAZARDS WHICH MAY BE ENCOUNTERED. STRICT ADHERENCE TO THE HEALTH AND SAFETY GUIDELINES SET FORTH HEREIN WILL REDUCE, BUT NOT ELIMINATE, THE POTENTIAL FOR INJURY AT THIS SITE. THE HEALTH AND SAFETY GUIDELINES IN THIS PLAN WERE PREPARED SPECIFICALLY FOR THIS SITE AND SHOULD NOT BE USED ON ANY OTHER SITE WITHOUT PRIOR RESEARCH BY TRAINED HEALTH AND SAFETY SPECIALISTS.

Project Name: RCRA Facility Assessments Project No.: EPA 4236.315 TCKS

Purpose of Visit:

A visual site inspection for the purposes of completing the RCRA Facility Assessment (RFA) will be conducted. No sampling activities will be conducted only visual inspection of the Solid Waste Management Units. In addition, files will be ~~be~~ reviewed for background material in the PR EQB Headquarters in San Juan.

Site Visit Personnel:

Donna Coker

John Inglis

Donna Coker

John Inglis

Responsibility:

Site Manager

HSO

Emergency Information:

<u>Type</u>	<u>Name</u>	<u>Phone Nos.</u>
Police:	<u>To Be Determined</u>	
Ambulance:	<u>TBD</u>	
Hospital:	<u>TBD</u>	
Rescue Service:	<u>TBD</u>	
CHSS:	<u>TBD</u>	
Site Manager:	<u>TBD</u>	
HSM:	<u>TBD</u>	

Hospital Route:

TBD

Site Background/Hazard Assessment:

Eli Lilly Inc. Mayaguez Plant manufactures pharmaceutical compounds. Five final products are manufactured in bulk. The plant also receives hazardous waste from the Carolina, PR Plant. There are 5 Solid Waste Management Units on site, an incinerator, drum storage area and waste water treatment plant. Waste constituents on the facility include halogenated and nonhalogenated solvents and wastes containing various metals. Waste generation and treatment occurs as batch operations, therefore, several of the storage tanks may be empty at any time. Generally, the potential hazard to personnel is minimal.

PPE Requirements:


Ebasco personnel will adhere to the health and safety policy established by Eli Lilly to protect company personnel and visitors at the facility. This will probably require PPE such as safety boots, glasses and hat to be worn during inspection.

Monitoring Equipment and Calibration Information:

None Required

Approvals

By their signature the undersigned certify that this HASP is approved and will be utilized at the Eli Lilly Industries site.


Site Manager

7/31/87
Date



Steve Schaffer / Joe Sbarra
Company Health and Safety
Supervisor

7/31/87
Date

REM III Health and Safety
Manager

Date

I certify that I have read and understand this Health and Safety Plan. I further certify that in consideration of entrance permission to this site for bid purposes I will faithfully follow all instructions of the Site Health and Safety Officer designated for this visit.

 / 
Signature

Donna Cowher John Inglis
Name (Printed)

Ebarco
Company

7/31/87
Date